

EU Regulation 1907/2006 (REACH) Article 33 Communication

Date: Apr. 2018

The substance(s) listed below may be contained in these products above the threshold level of 0.1% by weight of the listed article. The substance(s) listed do not pose a safety risk, as long as the articles are used as intended, and any repair, servicing and maintenance are carried out following technical instructions and industry standard good practices.

Commercial and Public Escalators and Moving Walks

Dispose of all parts in accordance with applicable regulations.				
Sub-system	Component	Candidate List July 2017 Substance Name (contains or may contain)	CAS #	Additional Safe Use Information
Handrail	Handrail	Bis (2-ethylhexyl)phthalate	117-81-7	
Circuit Boards	Microchips	Hexahydromethylphthalic anhydride	25550-51-0	
	Ceramic Chip Filters, Ceramic Resonators	Lead Titanium Zirconium Oxide [(Pbx Tiy Zrz)O3] or PbTiO3	12626-81-2	
	Oscillators, Crystal (surface mount)	Lead Titanium trioxide (PbTiO3)	12060-00-3	
Brake circuit board	Resistor	Lead Titanium Zirconium Oxide [(Pbx Tiy Zrz)O3]	12626-81-2	
Electrical tape	electrical tape	Bis (2-ethylhexyl)phthalate	117-81-7	
		Benzyl butyl phthalate	85-68-7	
		Diisobutyl phthalate	84-69-5	
		2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa- 3,5-dithia-4-stannatetradecanoate	15571-58-1	
		2-ethylhexyl 10-ethyl-4-[[2-[(2-ethylhexyl)oxy]- 2-oxoethyl]thio]-4- octyl-7-oxo-8-oxa-3,5- dithia-4-stannatetradecanoate	27107-89-7	
Insulation in motors, windings, power supplies, etc.	Insulation tape	N,N-dimethylacetamide	127-19-5	
	Cable jackets	N,N-dimethylacetamide	127-19-5	
Motor stator /Brake coils	Wire Coatings	1-Methyl-2-pyrrolidone (NMP)	872-50-4	
Wiring	Cable Insulation(PVC)	Bis (2-ethylhexyl)phthalate	117-81-7	
		Benzyl butyl phthalate	85-68-7	
		Diisobutyl phthalate	84-69-5	
Lighting	LED	Hexahydromethylphthalic anhydride	25550-51-0	
Detection sensor	Piezoelectric sensor	Lead Titanium Zirconium Oxide [(Pbx Tiy Zrz)O3]	12626-81-2	

Version 1.0